

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re patent of:

Baumer *et al.*

Patent. No.: 7,373,561 B2

Issued: May 13, 2008

For: **Integrated Packet Bit Error Rate  
Tester for 10G SERDES**

Confirmation No.: 7513

Art Unit: 2117

Examiner: Gandhi, Dipakkumar B.

Atty. Docket: 1875.4430000

**Request for Certificate of Correction  
Under 37 C.F.R. § 1.322**

*Attn: Certificate of Correction Branch*

Commissioner for Patents  
PO Box 1450  
Alexandria, VA 22313-1450

Sir:

It is hereby requested that a Certificate of Correction under 37 C.F.R. § 1.322 be issued for the above-captioned United States Patent. This Certificate of Correction is being requested due to mistakes which appear in the printed patent. These mistakes were made by the U.S. Patent and Trademark Office.

Specifically, the printed patent contains the following error for which a Certificate of Correction is respectfully requested:

In column 17, line 32, "redundancy cheek" should be replaced with --redundancy check--.

***Remarks***

The above-noted correction does not involve such changes in the patent as would constitute new matter or would require reexamination.

A completed Form PTO/SB/44 accompanies this request, with the above-noted correction printed thereon. Accordingly, a Certificate of Correction is believed proper and issuance thereof is respectfully requested.

The Commissioner is hereby authorized to charge any fee deficiency, or credit any overpayment, to our Deposit Account No. 19-0036.

Respectfully submitted,

STERNE, KESSLER, GOLDSTEIN & FOX P.L.L.C.

James J. Pohl  
Attorney for Patentees  
Registration No. 60,724

Date: April 15, 2009

1100 New York Avenue, N.W.  
Washington, D.C. 20005-3934  
(202) 371-2600

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

PATENT NO. : 7,373,561 B2

Page 1 of 1

APPLICATION NO.: 10/681,244

ISSUE DATE : May 13, 2008

INVENTOR(S) : Howard A. Baumer et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 17, line 32, "redundancy cheek" should be replaced with --redundancy check--.

**MAILING ADDRESS OF SENDER (Please do not use customer number below):**

Sterne, Kessler, Goldstein & Fox P.L.L.C.  
1100 New York Avenue, N.W.  
Washington, DC 20005-3934

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.